




*Fig. 1*









*Fig. 2a*




**Fig. 26**




*Fig. 5*




*Fig. 6*




*Fig. 7*




*Fig. 8*




*Fig. 9*




*Fig. 10*




*Fig. 11*







*Fig. 13*




*Fig. 14*



*Fig. 15*




*Fig. 16*



*Fig. 17*





*Fig. 18*

Claims ID# 20000307135816000127

Dealership Mashni Motor Company

P & A Code 1

Submitted By Dave G Park

Reviewer Jeremy Willard

Date 3/7/00 1:57 PM EST

Status New

RO Number 563214

VIN 1ZWHT61L9X5650604

Make

Model

Model Year

KILOMETERS 15632

NEW

Repair line item 1

Claim Status Approved

ACES Code P17JW

Symptom Code ☒

Customer Waiting ☐

Parts on Hand ☐

Paint ☐

Description

Digital Imaging

512

516

518

514

521

520

Camera Docked

Receive Claimset

Next

Reset

Send Claimset

120

120

140

150

MPH

12:54

015632

120

130

140

150

MPH

12:54

015632

1ZWHT61L9X5650604

3/8/2000 1:44am

Fig. 19a

500




Fig. 19b